General Environmental Incident Summary

Incident: 3993 Date/Time Notice: 12/31/2015 1600 ? DEM Incident No:

Responsible Party: E&B trucking inc

Date Incident:12/31/2015Time Incident:1500Duration:County:GrantTwp:134Rng:89Sec:29Qtr:Lat:46.39615Long:-101.89840Method:Interpolation from map

Location Description: mile marker 12 south on hwy 49 south of New Leipzig by mile marker 12

Submitted By: steven oxton Affiliation: truck owner

Address: 3939 7th ave n

City: fargo State: ND Zip: 58102

Received By:

Contact Person: steven oxton

3939 7th ave n fargo, ND 58102

Distance Nearest Occupied Building: Release Contained: Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: cattle feed (molasses)

Volume Spilled: 3000.00 gallons Ag Related: Yes

EPA Extremely Hazardous Substance: No Reported to NRC: Unknown

Cause of Incident: truck overturned

Risk Evaluation:

no

of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:

none

Action Taken or Planned:

trying to get someone to get a skid steer to clean-up, from around that area

Wastes Disposal Location: at a feed lot or farm ,I would think

Agencies Involved: Local Law Enforcement, Local Emergency Manager

Friday, January 27, 2017 Page 1 of 2

Updates

Date: 1/4/2016 Status: Reviewed - Follow-up Required Author: Washek, Sandi

Updated Volume: 3000.00 gallons

Notes:

Change made on location of spill. New location is updated to 1 mile south of New Leipzig on Hwy 49 near mile marker 12.

Date: 1/4/2016 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, 3000 gallons of molasses were released along a roadway. More followup needed.

Date: 1/6/2016 Status: Correspondence Author: Espe, Brady

Updated Volume:

Notes:

Received email with the breakdown of the molasses that was lost in the accident.

Date: 1/7/2016 Status: Inspection Author: Espe, Brady

Updated Volume:

Notes:

I arrived at the site at 12:47 p.m. The weather was overcast and 18°F, with wind from the southeast 0-5 mph. The accident occurred on the east side of ditch in between mile marker 12 and 13 located near the South Dakota border. There are a couple of stained areas in the ditch. The tank appears to have landed next to the fence line. The product also ran onto the land next to the ditch, covering parts of an area approximately 50' by 100'. There were a couple of areas of standing product, and there was a strip along the fence line approximately 1' by 50'. Most of the product had soaked into the vegetation and top few inches of soil. More follow-up is needed next growing season. 46.12740, -101.95723

Friday, January 27, 2017 Page 2 of 2